

Current klipper setup

currently how we have the printers set up.

Modifications testing automattions etc.

- [current troubleshooting](#)

current troubleshooting

Filament runout sensor-

The runout sensor triggers once and pauses the print. seemingly this does not occur again when it triggers a second time.

We need to test if we can still pause the print after the initial runout sensor in the case of longer prints. (this is currently inconclusive)