

TapeMeasure's Universal Mounting Plate

Specs (Measure the pockets to make sure nuts & bolts will fit)

- Nut & Bolt- 1/4" - 20
- Mounting point spacing 20 mm
- x27 Mounting points
- Plate's mounting point x6 160mm (aligned for Spot's T-slots)
- Overall Dimensions 180mm x 100 x 10mm

Models are available under attachments to the left to with the link below

[Mounting Plate on Printables](#)

Additional accessories

Print settings

When slicing the model make sure to have a layer pause before the pockets are sealed to place 1/4-20 bolts. Spot Universal Mounting Plate.3mf should have a layer pause set when using PrusaSlicer and the file is "opened as project".



Photos of accessories

Revision #8

Created 5 September 2024 22:53:22 by JoshuaFernando

Updated 9 November 2024 19:46:53 by JoshuaFernando